



## Instruction manual

### hps+ Ultrasonic Sensors for application in overpressure with two switched outputs

- hps+25/DD/TC/E/G1
- hps+35/DD/TC/E/G1
- hps+130/DD/TC/E/G1
- hps+340/DD/TC/E/G2
- hps+340/DD/TC/G2

### Product description

- The hps+ sensor measures the level in a vessel in up to 6 bar overpressure contactless. The G1 and G2 threaded pipe end permits the mounting and sealing of the sensor in a flange of the vessel. The pnp switched outputs are set according to the adjusted detect distances.
- The surfaces of the ultrasonic transducers of the hps+ sensors are protected by a PTFE film (Teflon film) and sealed with a FFKM O-ring against the sensor housing. Therefore the surface of the ultrasonic transducer can be cleaned from cakings or spots.
- All settings are done with two push-buttons and a three-digit LED-display (TouchControl).
- Light emitting diodes (three-colour LEDs) indicate all operation conditions.
- Choosing between output function NOC and NCC is possible.
- The sensors are adjustable manually using the numerical LED-display or may be trained using Teach-in processes.
- Useful additional functions are set in the Add-on-menu.
- With the LinkControl- Adapter LCA-2, available as accessory, all sensor settings

can be made optionally with a PC using the LinkControl software.

### Important instructions for assembly and application

All employee and plant safety-relevant measures must be taken prior to assembly, start-up or maintenance work (see operation manual for the entire plant and the operator instruction of the plant).

**The sensors are not considered as safety equipment and may not be used to ensure human or machine safety!**

The hps+ sensors indicate a **blind zone**, in which the distance cannot be measured. The **operating range** indicates the distance of the sensor that can be applied in normal atmospheric pressure with sufficient function reserve.

### Assembly instructions

- Assemble the sensor at the installation location.
- If necessary seal the sensor with the enclosed Viton O-ring (34 x 2,5 mm or 60 x 4 mm) against the flange.
- Plug in the connector cable to the M 12 connector.

	1	+U <sub>B</sub>	brown
	3	-U <sub>B</sub>	blue
	4	D2	black
	2	D1	white
	5	Sync/Com.	grey

Fig. 1: Pin assignment with view onto sensor plug and colour coding of the microsonic connection cable

### Start-up

- hps+ sensors are delivered factory made with the following settings:
- Switched outputs on NOC.
- Detecting distances at operating range and half operating range.

- Measurement range set to maximum range.
- Sensitivity at Normal pressure.

Set the parameters of the sensor manually or use the Teach-in procedure to adjust the detect points.




Fig. 2: TouchControl


### Operation

hps+ sensors work maintenance free. Small amounts of dirt on the surface do not influence function. Thick layers of dirt and caked-on dirt affect the sensor function and therefore must be removed.

### Note

- In operation in overpressure it is recommended to adjust the sensitivity of the hps+ sensor: choose the parameter A14 in the Add-on menu and set it to sensitivity E2 for atmospheric pressure from 1 to 3 bar or to sensitivity E3 for atmospheric pressure > 3 bar.
- hps+ sensors have internal temperature compensation. Because the sensors heat up on their own, the temperature compensation reaches its optimum working point after approx. 30 minutes of operation.
- During normal mode operation, a yellow LED signals that the corresponding switched output has connected.
- During normal mode operation, the measured distance value is displayed on the LED-indicator in mm (up to 999 mm) or cm (from 100 cm). Scale switches automatically and is indicated by a point on top of the digits.
- During Teach-in mode, the hysteresis loops are set back to factory settings.
- If no objects are placed within the detection zone the LED-indicator shows »-«.
- If no push-buttons are pressed for 20 seconds during parameter setting mode the made changes are stored and the sensor returns to normal mode operation.

## Set sensor parameters alternatively numerically using LED-display...



### Show parameters

Tapping push-button T1 shortly during normal mode operation shows »PAR« on the LED-display. Each time you tap push-button T1 the actual settings of the analogue output and the switched output are shown.

# ...or with the Teach-in procedure

**Teach-in switched output D1**

**Teach-in switched output D2**

# Key lock and factory setting

**Normal mode operation**

# Usefull additional functions in Add-on menu (for experienced users only, settings not required for standard applications)

**Start here**

HELLO Pro **Add-on**


Press T1 and T2 simultaneously for about 13 s until »Add« is shown in the LED-display

**Ready**

- Low power mode**
  - »C01«: Display bright
  - »C02«: Display dimmed
  - »C03«: Display off
- Hysteresis switched output D1**
  - Minimum value: »001«
  - Maximum value: difference between maximum range and detect point - 1
  - During window mode operation hysteresis influences both detect points.
- Hysteresis switched output D2**
  - Minimum value: »001«
  - Maximum value: difference between maximum range and detect point - 1
  - During window mode operation hysteresis influences both detect points.
- Measurement filter**
  - »F00«: no filter
  - »F01«: standard filter
  - »F02«: averaging filter
  - »F03«: foreground filter
  - »F04«: background filter
- Filter strength**
  - Defines the strength of the chosen filter.
  - »P00«: weak filter up to
  - »P09«: strong filter
- Response time**
  - Delay in seconds between the detection of an object and the output of the measured distance in case of object approach (behaves as on-delay).
  - "00": 0 s (no delay) up to
  - "20": 20 s response time
- Foreground suppression**
  - Minimum value: blind zone
  - Maximum value: nearwindow limit - 1
- Multiplex mode device addressing**
  - »00«: synchronisation
  - »01« to »10«: sensor address for multiplex mode
  - »OFF«: synchronisation deactivated
- Multiplex mode highest address**
  - To optimize multiplex speed the highest sensor address may be set.
  - Setting range »01« to »10«
- Measurement range**
  - Minimum value: sensor-distant window margin
  - Maximum value: 999 mm for hps+25/..., hps+35/..., 999 cm for hps+130/..., hps+340/
- Calibration display**
  - Put plane reflector vertically disposed in front of sensor: in an exact distance of 250 mm for hps+25... and hps+35... and 900 mm for all other types. Adjust display to 250 mm or 900 mm. Confirm calibration with T1 + T2.
- Sensitivity**
  - Affects the sensitivity for operation in overpressure.
  - »E01«: normal pressure
  - »E02«: 1-3 bar overpressure
  - »E03«: > 3 bar overpressure

**Note**  
Changes in the Add-on menu may impair the sensor function.  
A6, A7, A8, A10, A11, A12 have influence on the response time of the sensor.

# Technical data



	hps+25...	hps+35...	hps+130...	hps+340...	hps+340...
<b>Blind zone</b>	0 to 30 mm	0 to 85 mm	0 to 200 mm	0 to 350 mm	0 to 350 mm
<b>Operating range</b>	250 mm	350 mm	1,300 mm	3,400 mm	3,400 mm
<b>Maximum range</b>	990 mm	1,500 mm	5,000 mm	8,000 mm	8,000 mm
<b>Angle of beam spread</b>	Please see detection zone	Please see detection zone	Please see detection zone	Please see detection zone	Please see detection zone
<b>Transducer frequency</b>	320 kHz	320 kHz	180 kHz	120 kHz	120 kHz
<b>Resolution, sampling rate</b>	0.025 mm	0.18 mm	0.18 mm	0.18 mm	0.18 mm
<b>Reproducibility</b>	± 0,15 %	± 0,15 %	± 0,15 %	± 0,15 %	± 0,15 %
<b>Accuracy</b>	Temperature drift internal compensated, ≤ 2 % may be deactivated <sup>1)</sup> (0,17%/K without compensation)	Temperature drift internal compensated, ≤ 2 % may be deactivated <sup>1)</sup> (0,17%/K without compensation)	Temperature drift internal compensated, ≤ 2 % may be deactivated <sup>1)</sup> (0,17%/K without compensation)	Temperature drift internal compensated, ≤ 2 % may be deactivated <sup>1)</sup> (0,17%/K without compensation)	Temperature drift internal compensated, ≤ 2 % may be deactivated <sup>1)</sup> (0,17%/K without compensation)
<b>Detection zones for different objects:</b> The dark grey areas are determined with a thin round bar and indicate the typical operating range of a sensor. In order to obtain the light grey areas, a plate (500 x 500 mm) is introduced into the beam spread from the side. In doing so, the optimum angle between plate and sensor is always employed. This therefore indicates the maximum detection zone of the sensor. It is not possible to evaluate ultrasonic reflections outside this area.					
Displayed is the detection zone at standard pressure. At 1 bar overpressure the sensitivity of the sensor will increase 5 times.					
<b>Operating voltage U<sub>B</sub></b>	9 V to 30 V DC, short-circuit-proof	9 V to 30 V DC, short-circuit-proof	9 V to 30 V DC, short-circuit-proof	9 V to 30 V DC, short-circuit-proof	9 V to 30 V DC, short-circuit-proof
<b>Voltage ripple</b>	±10 %	±10 %	±10 %	±10 %	±10 %
<b>No-load supply current</b>	≤ 80 mA	≤ 80 mA	≤ 80 mA	≤ 80 mA	≤ 80 mA
<b>Ambient pressure</b>	up to 6.0 bar	up to 6.0 bar	up to 6.0 bar	up to 6.0 bar	up to 6.0 bar
<b>Housing</b>	Stainless steel 1.4571, plastic parts: PBT, TPU; Ultrasonic transducer: PTFE film, FFKM O-ring	Stainless steel 1.4571, plastic parts: PBT, TPU; Ultrasonic transducer: PTFE film, FFKM O-ring	Stainless steel 1.4571, plastic parts: PBT, TPU; Ultrasonic transducer: PTFE film, FFKM O-ring	Stainless steel 1.4571, plastic parts: PBT, TPU; Ultrasonic transducer: PTFE film, FFKM O-ring	Stainless steel 1.4571, plastic parts: PBT, TPU; Ultrasonic transducer: PTFE film, FFKM O-ring
<b>Process connection</b>	G1	G1	G1	G2	G2
<b>Class of protection to EN 60529</b>	IP 67	IP 67	IP 67	IP 67	IP 67
<b>Norm conformity</b>	EN 60947-5-2	EN 60947-5-2	EN 60947-5-2	EN 60947-5-2	EN 60947-5-2
<b>Type of connection</b>	5-pin initiator plug, PBT	5-pin initiator plug, PBT	5-pin initiator plug, PBT	5-pin initiator plug, PBT	5-pin initiator plug, PBT
<b>Controls</b>	2 push-buttons (TouchControl)	2 push-buttons (TouchControl)	2 push-buttons (TouchControl)	2 push-buttons (TouchControl)	2 push-buttons (TouchControl)
<b>Indicators</b>	3-digit LED-display, 2 three-colour LEDs	3-digit LED-display, 2 three-colour LEDs	3-digit LED-display, 2 three-colour LEDs	3-digit LED-display, 2 three-colour LEDs	3-digit LED-display, 2 three-colour LEDs
<b>Programmable</b>	Yes, with TouchControl and LinkControl	Yes, with TouchControl and LinkControl	Yes, with TouchControl and LinkControl	Yes, with TouchControl and LinkControl	Yes, with TouchControl and LinkControl
<b>Operating temperature</b>	-25°C to +70°C	-25°C to +70°C	-25°C to +70°C	-25°C to +70°C	-25°C to +70°C
<b>Storage temperature</b>	-40°C to +85°C	-40°C to +85°C	-40°C to +85°C	-40°C to +85°C	-40°C to +85°C
<b>Weight</b>	210 g	210 g	210 g	1,200 g	350 g
<b>Switching hysteresis<sup>1)</sup></b>	3 mm	5 mm	20 mm	50 mm	50 mm
<b>switching frequency<sup>1)</sup></b>	11 Hz	9 Hz	5 Hz	3 Hz	3 Hz
<b>Response time<sup>1)</sup></b>	65 ms	84 ms	160 ms	240 ms	240 ms
<b>Time delay before availability</b>	< 300 ms	< 300 ms	< 300 ms	< 300 ms	< 300 ms
<b>Order No.</b>	hps+25/DD/TC/E/G1	hps+35/DD/TC/E/G1	hps+130/DD/TC/E/G1	hps+340/DD/TC/E/G2	hps+340/DD/TC/G2
<b>Switched output</b>	2 x pnp, U <sub>B</sub> - 2 V, I <sub>max</sub> = 2 x 200 mA switchable NOC/NCC, short-circuit-proof	2 x pnp, U <sub>B</sub> - 2 V, I <sub>max</sub> = 2 x 200 mA switchable NOC/NCC, short-circuit-proof	2 x pnp, U <sub>B</sub> - 2 V, I <sub>max</sub> = 2 x 200 mA switchable NOC/NCC, short-circuit-proof	2 x pnp, U <sub>B</sub> - 2 V, I <sub>max</sub> = 2 x 200 mA switchable NOC/NCC, short-circuit-proof	2 x pnp, U <sub>B</sub> - 2 V, I <sub>max</sub> = 2 x 200 mA switchable NOC/NCC, short-circuit-proof

1) Can be programmed with TouchControl and LinkControl

