
Positioning



When scanning panes of glass or other smooth, flat surfaces, care should be taken to ensure that the ultrasonic sensor scans perpendicular to the surface.

application areas

Logistics